

VCDS  
Windows Based VAG/VAS Emulator  
VCDS Version: Release 12.12.0 Data version: 20130910  
www.Ross-Tech.com

Dealer/Shop Name:  
Workshop Code: 000 00000 000000

Self-Diagnosis Log  
Tuesday,01,October,2013,23:36:28:40973

VIN: XW8ZZZ3CZ8G002584 License Plate: 22222  
Mileage: Repair Order:

Chassis Type: 3C (3C0)  
Scan: 01 02 03 08 09 11 31 15 16 17 19 25 42 44 46 52 53 62 72

VIN: XW8ZZZ3CZ8G002584

01-Engine -- Status: OK 0000  
02-Auto Trans -- Status: Cannot be reached 1100  
03-ABS Brakes -- Status: OK 0000  
04-Steering Angle -- Status: OK 0000  
08-Auto HVAC -- Status: Malfunction 1010  
09-Cent. Elect. -- Status: Malfunction 0010  
11-Engine II -- Status: Cannot be reached 1100  
31-Engine other -- Status: Cannot be reached 1100  
15-Airbags -- Status: OK 0000  
16-Steering wheel -- Status: OK 0000  
17-Instruments -- Status: Malfunction 0010  
19-CAN Gateway -- Status: Malfunction 0010  
25-Immobilizer -- Status: OK 0000  
42-Door Elect, Driver -- Status: OK 0000  
44-Steering Assist -- Status: OK 0000  
46-Central Conv. -- Status: Malfunction 0010  
52-Door Elect, Pass. -- Status: OK 0000  
53-Parking Brake -- Status: OK 0000  
62-Door, Rear Left -- Status: OK 0000  
72-Door, Rear Right -- Status: OK 0000

---

Address 01: Engine ( ) Labels: 06J-907-115-BZB.clb  
Part No SW: 06J 906 026 HW: 06J 906 026  
Component: MED17.5 1756  
Revision: A8H03--- Serial number: VWZCZ000000000  
Coding: 0404000318070160  
Shop #: WSC 00028 028 00001  
VCID: E7DDDD1ED6CD5926B59-80B2

No fault code found.  
Readiness: 0100 0101

---

Address 02: Auto Trans  
Cannot be reached

---

VCDS  
Self-Diagnosis Log  
Tuesday,01,October,2013,23:36:28:40973  
Page 2

VIN: XW8ZZZ3CZ8G002584 License Plate: 22222

Address 03: ABS Brakes Labels: 3C0-614-109-C4.clb  
Part No SW: 3C0 614 109 C HW: 3C0 614 109 C  
Component: J104 C4 440 V1 0003  
Revision: --020--- Serial number: 00000776795248  
Coding: 0004405  
Shop #: WSC 00028 028 00001  
VCID: 1E3338FAC917D8EE86F-804B

No fault code found.

---

Address 08: Auto HVAC (J255) Labels: 5K0-907-044.clb  
Part No SW: 5K0 907 044 ED HW: 5K0 907 044 ED  
Component: Climatronic H17 1010  
Revision: 00003001  
Coding: 0000000002  
Shop #: WSC 00028 028 00020  
ASAM Dataset: EV\_Climatronic A01010  
ROD: EV\_ClimaAutoBasis\_SE36.rod  
VCID: 71E93346A00917966BD-8024

1 Fault Found:

9480469 - Control Circuit for A/C Compressor  
B10A9 15 [009] - Open or Short to Plus  
Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001  
Fault Priority: 2  
Fault Frequency: 1  
Reset counter: 58  
Mileage: 35822 km  
Date: 2023.14.04  
Time: 20:19:58

---

VCDS  
Self-Diagnosis Log  
Tuesday,01,October,2013,23:36:28:40973  
Page 3

VIN: XW8ZZZ3CZ8G002584 License Plate: 22222

Address 09: Cent. Elect. Labels: 3C0-937-049-30-M.lbl  
Part No SW: 3C0 937 049 AK HW: 3C0 937 049 AK  
Component: Bordnetz-SG H54 2202  
Revision: 00H54000 Serial number: 01000005318841  
Coding: E484930700043A005700000050000000000D59405C000124000000000000  
Shop #: WSC 00028 028 00001  
VCID: 72EB3C4A6D0F2C8E927-8027

Subsystem 1 - Part No: 3C1 955 419 A Labels: 1KX-955-119.CLB  
Component: Wischer 201107 003 0205  
Coding: 00046997  
Shop #: WSC 00028

Subsystem 2 - Part No: 1K0 955 559 AF Labels: 1K0-955-559-AF.CLB  
Component: RLS 090108 046 0204  
Coding: 00208933  
Shop #: WSC 00028

2 Faults Found:

01320 - Control Module for Climatronic (J255)  
004 - No Signal/Communication - Intermittent  
Freeze Frame:  
Fault Status: 00100100  
Fault Priority: 2  
Fault Frequency: 3  
Reset counter: 150  
Mileage: 89784 km  
Time Indication: 0  
Date: 2005.09.13  
Time: 31:63:63

Freeze Frame:  
OFF  
Voltage: 13.00 V  
OFF  
ON  
OFF  
OFF  
OFF

02390 - Control / Regulation for Ambience Lighting (E400)  
009 - Open or Short to Ground  
Freeze Frame:  
Fault Status: 01101001  
Fault Priority: 5  
Fault Frequency: 1  
Reset counter: 110  
Mileage: 89784 km  
Time Indication: 0  
Date: 2005.09.13  
Time: 31:63:63

VCDS  
Self-Diagnosis Log  
Tuesday,01,October,2013,23:36:28:40973  
Page 4

VIN: XW8ZZZ3CZ8G002584 License Plate: 22222

Freeze Frame:

ON

Voltage: 14.05 V

ON

ON

OFF

OFF

OFF

---

Address 11: Engine II  
Cannot be reached

---

Address 15: Airbags Labels: 5N0-959-655.lbl  
Part No SW: 5N0 959 655 A HW: 5N0 959 655 A  
Component: J234\_005 VW10 HI 1815  
Revision: 19013000 Serial number: 0039DPPDMVY3  
Coding: 0012341  
Shop #: WSC 00028 028 00001  
VCID: 3B75D16E7AC5ADC6811-806E

Subsystem 1 - Serial number: 6333FTS625253437

Subsystem 2 - Serial number: 6343FTS630703447

Subsystem 3 - Serial number: 6353ETS611O3SVNP

Subsystem 4 - Serial number: 6363ETS60KH2SVNP

Subsystem 5 - Serial number: 000000000000000000

Subsystem 6 - Serial number: 000000000000000000

No fault code found.

---

Address 16: Steering wheel Labels: 3C0-953-549-SW20.lbl  
Part No SW: 3C0 953 549 AD HW: 3C0 953 549 AD  
Component: J0527 0020  
Revision: 00026000 Serial number: 3C5953507BA  
Coding: 0000013  
Shop #: WSC 00028 028 00001  
VCID: 6ED3283A7937086E76F-803B

No fault code found.

---

VCDS  
Self-Diagnosis Log  
Tuesday,01,October,2013,23:36:29:40973  
Page 5

VIN: XW8ZZZ3CZ8G002584 License Plate: 22222

Address 17: Instruments (J285) Labels: 3C8-920-xxx-17.clb  
Part No SW: 3AA 920 870 HW: 3AA 920 870  
Component: KOMBI H20 0420  
Serial number: 000000000000000  
Coding: 160D00  
Shop #: WSC 00028 028 00020  
ASAM Dataset: EV\_Kombi\_UDS\_VDD\_RM09 A04089  
ROD: EV\_Kombi\_UDS\_VDD\_RM09\_SE35.rod  
VCID: EFEDB53E363D8166FD9-80BA

1 Fault Found:

12648704 - Function Restricted due to Missing Message(s)

U1111 00 [009] - -

Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 6

Fault Frequency: 1

Reset counter: 110

Mileage: 38211 km

Date: 2024.14.29

Time: 00:35:58

---

VCDS  
Self-Diagnosis Log  
Tuesday, 01, October, 2013, 23:36:29:40973  
Page 6

VIN: XW8ZZZ3CZ8G002584 License Plate: 22222

Address 19: CAN Gateway Labels: 3C0-907-530-V2.clb  
Part No SW: 3C0 907 530 E HW: 3C0 907 951  
Component: J533\_\_Gateway H10 0080  
Revision: H10 Serial number: 1200P07C1800DB  
Coding: FF807F060000021002  
Shop #: WSC 00028 028 00001  
VCID: 2345090EE275F506A91-8076

4 Faults Found:

01315 - Transmission Control Module

004 - No Signal/Communication

Freeze Frame:

Fault Status: 01100100

Fault Priority: 2

Fault Frequency: 1

Reset counter: 110

Mileage: 89784 km

Time Indication: 0

Date: 2000.00.00

Time: 04:49:37

01342 - Engine Control Module 2 (Slave 1)

004 - No Signal/Communication

Freeze Frame:

Fault Status: 01100100

Fault Priority: 2

Fault Frequency: 1

Reset counter: 110

Mileage: 89784 km

Time Indication: 0

Date: 2000.00.00

Time: 04:49:37

01320 - Control Module for Climatronic (J255)

004 - No Signal/Communication - Intermittent

Freeze Frame:

Fault Status: 00100100

Fault Priority: 2

Fault Frequency: 3

Reset counter: 150

Mileage: 89784 km

Time Indication: 0

Date: 2000.00.00

Time: 04:57:11

00381 - Databus Instrument Cluster

004 - No Signal/Communication - Intermittent

Freeze Frame:

Fault Status: 00100100

Fault Priority: 1

Fault Frequency: 1

Reset counter: 150

VCDS  
Self-Diagnosis Log  
Tuesday,01,October,2013,23:36:29:40973  
Page 7

VIN: XW8ZZZ3CZ8G002584 License Plate: 22222

Time Indication: 15

---

Address 25: Immobilizer      Labels: 3C0-959-433-25.clb  
Part No SW: 3C0 959 433 R    HW: 3C0 959 433 R  
Component: IMMO      042 0383  
Revision: 00042000    Serial number: VWZCZ000000000  
Shop #: WSC 131071 1023 2097151  
VCID: 3979CB6670F99FD693D-806C

Subsystem 1 - Part No: 3C0 905 861 G  
Component: ELV      027 0380  
3C0905861G    ELV      027 0380

No fault code found.

---

Address 42: Door Elect, Driver      Labels: 1K0-959-701-MIN3.lbl  
Part No SW: 1K0 959 701 P    HW: 1K0 959 793 L  
Component: J386 TUEP-SG FT    1131  
Revision: 32008001    Serial number: 00000060979219  
Coding: 0000245  
Shop #: WSC 00028 028 00001  
VCID: 3B75D16E7AC5ADC6811-806E

No fault code found.

---

Address 44: Steering Assist      Labels: 1Kx-909-14x-44.clb  
Part No: 1K1 909 144 M  
Component: EPS\_ZFLS KI.133 H08 1901  
Shop #: WSC 00028 028 00001  
VCID: 3561C7565CE17BB6775-8060

No fault code found.

---

VCDS  
Self-Diagnosis Log  
Tuesday,01,October,2013,23:36:29:40973  
Page 8

VIN: XW8ZZZ3CZ8G002584 License Plate: 22222

Address 46: Central Conv. Labels: 3C0-959-433-46.clb  
Part No SW: 3C0 959 433 R HW: 3C0 959 433 R  
Component: KSG PQ46 ELV 042 0472  
Revision: 00042000 Serial number: VWZCZ000000000  
Coding: 19910A0001864E7230049D1D70084F0B607CA1  
Shop #: WSC 00101 935 56651  
VCID: 3979CB6670F99FD693D-806C

Subsystem 1 - Component: Sounder n.mounted

Subsystem 2 - Component: NGS n.mounted

Subsystem 3 - Component: IRUE n.mounted

1 Fault Found:

01320 - Control Module for Climatronic (J255)  
004 - No Signal/Communication - Intermittent  
Freeze Frame:  
Fault Status: 00100100  
Fault Priority: 4  
Fault Frequency: 1  
Reset counter: 150  
Mileage: 38211 km  
Time Indication: 0  
Date: 2024.14.29  
Time: 00:44:27

---

Address 52: Door Elect, Pass. Labels: 1K0-959-702-MIN3.lbl  
Part No SW: 1K0 959 702 P HW: 1K0 959 792 L  
Component: J387 TUEP-SG BT 1131  
Revision: 32008001 Serial number: 00000740079218  
Coding: 0000244  
Shop #: WSC 00028 028 00001  
VCID: 3C77D2727FCBAAFE88B-8069

No fault code found.

---

Address 53: Parking Brake Labels: 5N0-907-801.clb  
Part No SW: 3C0 907 801 J HW: 3C0 907 801 J  
Component: J540 EPB3 VW-09393 0009  
Revision: 008 Serial number: 00000000302362  
Coding: 0000056  
Shop #: WSC 00028 028 00001  
VCID: 29591B2680592F56E3D-807C

No fault code found.

---



VCDS  
Self-Diagnosis Log  
Tuesday,01,October,2013,23:36:29:40973  
Page 9

VIN: XW8ZZZ3CZ8G002584 License Plate: 22222

Address 62: Door, Rear Left      Labels: 1K0-959-703-GEN3.lbl  
Part No SW: 1K0 959 703 AB    HW: 1K0 959 795 L  
Component: J388    TUER-SG HL    0308  
Revision: 41004101    Serial number: 00000000131035  
Coding: 0000208  
Shop #: WSC 00028 028 00001  
VCID: 70EF364263031E9E643-8025

No fault code found.

-----  
Address 72: Door, Rear Right      Labels: 1K0-959-704-GEN3.lbl  
Part No SW: 1K0 959 704 AB    HW: 1K0 959 794 L  
Component: J389    TUER-SG HR    0308  
Revision: 41004101    Serial number: 00000000140176  
Coding: 0000208  
Shop #: WSC 00028 028 00001  
VCID: 71E93346680917966BD-8024

No fault code found.

End -----